

THE POST PROJECT


February 15, 2019

WHERE WE WERE

NOV - DEC 2018



Canada Post building before construction




1 Asphalt and concrete topping being removed

2 Passenger elevator roof removal

WHERE WE ARE

FEB 2019



3 Opening in building for north tower elevator banks

4 Supports for tower cranes

5 Opening in building for circular vehicle ramp



5 Opening in building for circular vehicle ramp

6 Outline of south tower