


WHERE WE WERE




Canada Post building before construction

NOV - DEC 2018




- 1 Asphalt and concrete topping being removed
- 2 Passenger elevator roof removal

MARCH 2019



- 3 Opening in building for circular vehicle ramp
- 4 Outline of south tower
- 5 Opening in building for south tower elevator banks

WHERE WE ARE



- 6 Opening in building for circular vehicle ramp
- 7 Tower Cranes
- 8 Opening in building for north tower
- 9 Opening in building for south tower