


WHERE WE WERE



Canada Post building before construction


NOV - DEC 2018



1 Asphalt and concrete topping being removed

2 Passenger elevator roof removal

MARCH 2019




3 Opening in building for circular vehicle ramp

5 Opening in building for south tower elevator banks

4 Outline of south tower

WHERE WE ARE



6 Opening in building for circular vehicle ramp

8 Opening in building for north tower

7 Tower Cranes

9 Opening in building for south tower