


WHERE WE WERE




Canada Post building before construction

NOV - DEC 2018




- 1 Asphalt and concrete topping being removed
- 2 Passenger elevator roof removal

MARCH 2019



- 3 Opening in building for circular vehicle ramp
- 4 Outline of south tower
- 5 Opening in building for south tower elevator banks
- 6 Circular vehicle ramp coming out of main structure

WHERE WE ARE



- 7 Tower Cranes
- 8 Opening in building for north tower
- 9 South tower on its way out of the structure
- 10 Circular vehicle ramp coming out of main structure
- 11 Opening in building for south tower
- 12 Opening in building for north tower
- 13 Opening in building for south tower
- 14 Opening in building for north tower
- 15 Opening in building for south tower