

Radon

Ten residential buildings are located at the Property. Of these, all contain ground floor residential units. At the time of site reconnaissance, one radon canister was placed on the ground floor of each residential building located at the Property. The canisters were collected by Jessica Hirsch and forwarded for analysis.

Analytical results were found in excess of the EPA-recommended action level of 4.0 pCi/l in Unit 9-105. Re-sampling is recommended in order to evaluate potential environmental variables or equipment failure.

Location	Sample #	Results	Comments
1- 104	123650	1.4 pCi/L	
3- 103	123697	1.2 pCi/L	
5- 108	123659	1.7 pCi/L	
7- 102	123768	1.5 pCi/L	
9- 105	123823	4.0 pCi/L	At EPA's Action level of 4.0 pCi/L
11- 107	123744	2.4 pCi/L	
13- 106	123801	2.1 pCi/L	
19- 106	123746	1.4 pCi/L	
17- 101	123754	1.8 pCi/L	
15- 107	123709	2.1 pCi/L	

Analytical results were found in excess of the EPA-recommended action level of 4.0 pCi/l in Unit 9-105. Re-sampling is recommended in order to evaluate potential environmental variables or equipment failure.