

# Zephyr Contract Services

**Type** 48 Hour Continuous Monitor Test  
**Device** Sun Nuclear®  
**Conducted By** Zephyr Inspections

# RADON MEASUREMENT DATA

August 12, 2020  
 Continuous Radon Monitor

## SUMMARY

1430 Pine Grove Road, Building C, Steamboat Springs, CO 80487

	<u>pCi/L</u>	<u>EPA average</u>
Unit 101	2.4	2.5
Unit 102	1.7	1.8
Unit 103	2.4	2.5
Unit 104	1.1	1.1
Unit 105	1.7	1.8
Unit 106	4.1	4.3
Unit 107	2.2	2.2
Unit 108	4.9	5.1

## SUMMARY

1420 Pine Grove Road, Building B, Steamboat Springs, CO 80487

	<u>Overall</u>	<u>EPA average</u>
Unit 101	1.3	1.4
Unit 102	2.1	1.9
Unit 103	1.6	1.6
Unit 104	1.8	1.9
Unit 105	1.2	1.2
Unit 106	2.3	2.5
Unit 107	1.6	1.6
Unit 108	1.7	1.8

## SUMMARY

1410 Pine Grove Road, Building A, Steamboat Springs, CO 80487

	<u>Overall</u>	<u>EPA average</u>
Unit 101	0.8	0.8
Unit 102	2.2	2.2
Unit 103	2.1	2.1
Unit 104	2.2	2.1
Unit 105	1.9	2
Unit 106	15.3	15.2
Unit 107	2.1	2.2
Unit 108	12	11.9